


Erratum

Operation Manual 2YM15, 2YM20, 3YM30E, 3YM30. 3rd edition 1st rev.: June 2013.

On the subject 'Setup Screen Access and Control', on page 21, Speed Pulse Value of YM with VALEO Alternator shows 12.41. This is not correct, this should be 12.10.

Engine Model	Speed pulse value
YM with HITACHI alternator	10.29
YM with VALEO alternator	12.41 12.10

On the same page, on step 6 in setting the engine speed pulse value for B20/C30 type panel, illustration 6 shows P12.41 which is not correct, this should be P12.10.



Our sincere apologies.